

# SUMMARY MATERIALS

engineering, science, processing and design *third edition*

*Michael Ashby, Hugh Shercliff and David Cebon*

Bas Comuth



*Last edit: 19-1-2019*

**Disclaimer** *This document was prepared as a summary for myself. However, it might be useful for other students as well, which is why it was published online. No rights can be claimed, the author is not responsible for any wrong information spread through this document, or the lack of any information. Also, the author is not affiliated to TU Delft in any other kind than being a student.*

# Contents

<b>Chapter 1</b>	<b>3</b>
1.1 Materials, processes and choice	4
1.2 Material properties	4
1.3 Design-limiting properties	5
<b>Chapter 2</b>	<b>6</b>
2.1 Introduction and synopsis	7
2.2 Getting materials organised: the materials tree	7
2.3 Organising processes: the process tree	7
2.4 Process-property interaction	8
2.5 Material property charts	8
2.6 Computer-aided information management for materials and processes	8
<b>Chapter 3</b>	<b>9</b>
3.1 Introduction and synopsis	10
3.2 The design process	10
3.3 Material and process information for design	10
3.4 The strategy: translation, screening, ranking and documentation	10
<b>Chapter 4</b>	<b>12</b>
4.1 Introduction and synopsis	13
4.2 Density, stress, strain and moduli	13
4.3 The big picture: material property charts	15
4.4 The science: what determines stiffness and density	15
4.5 Manipulating the modulus and density	18
4.6 Acoustic properties	19
<b>Chapter 5</b>	<b>21</b>
5.1 Introduction and synopsis	22
5.2 Standard solutions to elastic problems	22
5.3 Material indices for elastic design	24
5.4 Plotting limits and indices on charts	26
5.5 Case studies	26
<b>Chapter 6</b>	<b>27</b>
6.1 Introduction and synopsis	28
6.2 Strength, plastic work and ductility: definition and measurement	28
6.3 The big picture: charts for yield strength	29
6.4 Drilling down: the origins of strength and ductility	29
6.5 Manipulating strength	31
<b>Chapter 7</b>	<b>33</b>
7.1 Introduction and synopsis	34

7.2 Standard solutions to plastic problems	34
7.3 Material indices for yield-limited design	35
7.4 Case studies	36
<b>Chapter 8</b>	<b>37</b>
8.1 Introduction and synopsis	38
8.2 Strength and toughness	38
8.3 The mechanics of fracture	38
8.4 Material property charts for toughness	39
8.5 Drilling down: the origins of toughness	40
8.6 Compressive and tensile failure of ceramics	40
8.7 Manipulating properties: the strength-toughness trade-off	41
<b>Chapter 9</b>	<b>42</b>
9.1 Introduction and synopsis	43
9.2 Vibration and resonance: the damping coefficient	43
9.3 Fatigue	43
9.4 Charts for endurance limit	44
9.5 Drilling down: the origins of damping and fatigue	44
9.6 Manipulating resistance to fatigue	45
<b>Chapter 10</b>	<b>46</b>
10.1 Introduction and synopsis	47
10.2 Standard solutions to fracture problems	47
10.3 Material indices for fracture-safe design	47
10.4 Case studies	47
<b>Chapter 12</b>	<b>49</b>
12.1 Introduction and synopsis	50
12.2 Thermal properties: definition and measurement	50
12.3 The big picture: thermal property charts	50
12.4 Drilling down: the physics of thermal properties	51
12.5 Manipulating thermal properties	51
12.6 Design and manufacture: using thermal properties	52
<b>Chapter 13</b>	<b>54</b>
13.1 Introduction and synopsis	55
13.2 The temperature dependence of material properties	55
13.3 Charts for creep behaviour	56
13.4 The science: diffusion	56

# **Chapter 1**

*Introduction: Materials - history and character*

## 1.1 Materials, processes and choice

Engineers make **things**. They make them out of **materials**, and they shape, join and finish them using **processes**.

## 1.2 Material properties

Properties of materials that have something to do with carrying a load safely are called **mechanical properties**. One of those properties is **stiffness**, or resistance to bending if you like, and it is represented by the **elastic modulus  $E$** . Another one is **strength**, or the ease with which a material can be permanently bent. Metals have a **yield strength  $\sigma_y$**  at which they will plastically deform. When metals deform, they generally get stronger (**work hardening**), but there is an ultimate limit, called the **tensile strength  $\sigma_{ts}$** , beyond which the material fails. High **hardness  $H$**  gives scratch resistance and resistance to wear. The resistance of materials to cracking and fracture is measured by the **fracture toughness  $K_{Ic}$** . One obvious material property is **density  $\rho$** , or mass per unit volume.

A material also has **thermal properties**. It has a **maximum service temperature  $T_{max}$** , above which its use is impractical. Most materials expand when they are heated, but by differing amounts depending on their **thermal expansion coefficient  $\alpha$** . **Thermal conductivity  $\lambda$** , measures the rate at which heat flows through the material when one side is hot and the other cold. **Heat capacity  $C_p$**  measures the amount of heat that it takes to make the temperature of material rise by a given amount. The **thermal diffusivity  $a$**  is how quickly the heat will spread through a material, and it is proportional to  $\lambda/C_p$ .

Let us now look at **electrical, magnetic and optical properties**. **Electrical conductivity  $\kappa_e$** , how easy it is for an electric current to flow through a material, and its inverse **resistivity  $\rho_e$** , how hard it is for an electric current to flow through a material, are both electrical properties. **Dielectric properties** are in some cases important to consider. Materials with a high **dielectric constant  $\epsilon_p$**  have electrons which are very sensitive to an electric field.

Materials that have the capacity to trap a magnetic field permanently are called **ferri-magnets** and **ferro-magnets**. We will consider two magnetic properties in this chapter: **remanence** and **saturation magnetization**. Remanence measures how easily a material can be demagnetized, once magnetized. Saturation magnetization measures how large a field the material can conduct.

Materials can also respond to light. Opaque materials **reflect** light, transparent materials **refract** it and some materials have the ability to **absorb** certain wavelengths.

Let's move on to **chemical properties**. We regard the intrinsic resistance of a material to for instance corrosion (oxidation), organic solvents, acids and alkalis or ultra-violet radiation as material properties, measured on a scale of 1 (very poor) to 5 (very good).

Last but certainly not least we have **environmental properties**. An engineer must also consider material efficiency and sustainability, and also the sustainability of the processes needed to fabricate these materials.

### 1.3 Design-limiting properties

The performance of a component is limited by certain of the properties of the materials of which it is made. This means that, to achieve a desired level of performance, the values of the **design-limiting properties** must meet certain targets, and those that fail to do so are not suitable.

## **Chapter 2**

*Family trees: organising materials and processes*

## 2.1 Introduction and synopsis

Processes and materials can be organised in **families**. Family likenesses are most strikingly seen in **material property charts**. Another way of organising materials or processes is **classification**.

## 2.2 Getting materials organised: the materials tree

It is conventional to classify the materials of engineering into the six broad families: **metals, polymers, elastomers, ceramics, glasses** and **hybrids** (composite materials made by combining two or more of the other families). Families can be expanded to show classes, sub-classes and members, each of which is characterised by its properties.

Metals are characterised by relatively high stiffness, fracture toughness and electrical and thermal conductivity. Most when pure have a low yield strength, which can be increased by hardening them. They will remain ductile. Metals are also very reactive, and corrode rapidly.

Ceramics are **non-metallic**, inorganic solids. They are stiff, hard abrasion-resistant (a high maximum service temperature), they resist corrosion well and they are good electrical insulators. However, they have a low fracture toughness.

Glasses are **non-crystalline (amorphous)** solids. They are hard and remarkably corrosion resistant. Glasses are excellent electrical insulators and are transparent to light. On the other hand glasses are very brittle and vulnerable to stress concentrations.

Polymers are organic solids based on long chains of carbon atoms. They are light, have a low stiffness, a low service temperature and easy to shape. They can be strong though, and because of their low density, their **specific strength** (strength per unit weight) is surprisingly high.

Elastomers are polymers with the unique property that their stiffness is extremely low, which causes them to be able to be stretched to many times their starting length. Despite this property they can be strong and tough.

Hybrids are combinations of two or more materials in an attempt to get the best of both. This causes them to have attractive properties. Nonetheless they are expensive and relatively difficult to form and join.

## 2.3 Organising processes: the process tree

A **process** is a method of shaping, joining or finishing a material. The choice of a process will be based on the **design requirements** and the type of material. Manufacturing processes are organised in: **primary shaping, secondary processes, joining** and **surface**

**treatment** (primary shaping and secondary processes both belong to the family 'shaping'). Examples of the first are **casting, molding, deformation, powder methods, composite forming** or other special methods. Secondary processes are **machining** and **heat treatment**. Some joining methods are **fastening, riveting, welding, heat bonding, snap fits, friction bonds, adhesives** cements. Examples of the latter are **polishing, texturing, plating, metallizing, anodizing, chromizing, painting** and **printing**.

## 2.4 Process-property interaction

Both processing and joining can change the properties of the materials.

## 2.5 Material property charts

A way to put materials in perspective and compare them is to use **material property charts** (either bar charts or bubble charts). In most charts a logarithmic scale is used. A bar chart is used to plot one physical quantity, a bubble chart to plot two. These charts are often used in the studies of materials.

## 2.6 Computer-aided information management for materials and processes

Materials and processes can also be organised in computer systems.

## **Chapter 3**

*Strategic thinking: matching material to design*

## 3.1 Introduction and synopsis

Design starts with a **market need**, which is analysed and expressed as design requirements. **Concepts** then are sought, developed (**embodied**), and refined (**detailed**) to give a **product specification**. Selection strategy involves **translation, screening, ranking and documentation**.

## 3.2 The design process

**Original design** starts from a new concept and develops the information necessary to implement it. **Evolutionary design** or **redesign** starts with an existing product and seeks to change it in ways that increase its performance or/and reduce its cost. Some scenarios that call for redesign are:

- **Product recall**: if a product, once released to the market, fails to meet safety standards, urgent redesign is required.
- **Poor value for money**: the product performs safely but offers performance that, at its price, is perceived to be mediocre, requiring redesign to enhance performance.
- **Inadequate profit margin**: the cost of manufacture exceeds the price that the market will bear.
- **Sustainable technology**: the response of the designer to the profligate use of materials in products and packaging, and to consumer pressure for production that does not harm the environment.
- **Mac-effect**: in a market environment in which many almost-identical products compete for the consumer's attention, it is style, image and character (industrial design) that sets some products above others.

## 3.3 Material and process information for design

Selection of process is analogue to and influenced by the selection of materials. It is also influenced by the requirements for shape.

## 3.4 The strategy: translation, screening, ranking and documentation

The first task is that of translation: converting the design requirements into a prescription for selecting a material. This proceeds by identifying the **constraint** that the material must meet and the **objectives** that the design must fulfil. The second task, then, is that of screening: eliminating the materials that cannot meet the constraint. This is followed by the ranking step: ordering the survivors by their ability to meet a criterion of excellence, such as that of minimising cost. The final task is to explore the most promising candidates in depth, a step we call documentation. Process selection follows a parallel route, but in that case translation

means identifying the geometric and other constraints that must be met. The designer is free to vary dimensions that are not constrained by design requirements and, most importantly, free to choose the material for the component and the process to shape it. We refer to these as **free variables**.

## **Chapter 4**

*Stiffness and weight: density and elastic moduli*

## 4.1 Introduction and synopsis

**Stress** causes strain. If you are human, the ability to cope with stress without undue **strain** is called **resilience**. If you are a material, it is called **elastic modulus**. Strain, a change of shape is a response to stress (something that is applied to a material by loading it). It depends on the magnitude of the stress and the way it is applied (the **mode of loading**). **Stiffness** is the resistance to change of shape that is **elastic**, meaning that the material returns to its original shape when the stress is removed. **Strength** is its resistance to permanent distortion or total failure. Both are material properties.

## 4.2 Density, stress, strain and moduli

In most cases, a component can be idealised as one of the simply loaded cases, a tie, column, beam, shaft or shell. Ties carry simple axial tension, columns compression. Bending of a beam creates simple axial tension in elements on one side of the neutral axis and simple compression in those on the other. Pressure difference applied to a shell generates bi-axial tension or compression.

Every plane normal to a force  $F$  carries that force. If the area of such a plane is  $A$ , the tensile stress in the element (neglecting its own weight) is

$$\sigma = \frac{F}{A}$$

If the sign of  $F$  is reversed, the stress is compressive and given a negative sign. If, instead, the force lies parallel to the face of the element, three other forces are needed to maintain equilibrium. They create a state of shear in the element. Shear stress is given by

$$\tau = \frac{F_s}{A}$$

One further state of multi-axial stress is produced by applying equal tensile or compressive forces to all six faces of a cubic element. The state of stress is one of hydrostatic pressure  $p$ . Notice that pressures are positive when they 'push', the reverse of the convention for simple tension and compression.

A tensile stress applied to an element causes the element to stretch. If the element originally of length  $L_0$ , stretches by  $\delta L = L - L_0$ , the nominal **tensile strain** is

$$\epsilon = \frac{\delta L}{L_0}$$

A shear stress causes a shear strain  $\gamma$ . If the element shears (sideways) by a distance  $w$ , the **shear strain** is

$$\tan(\gamma) = \frac{w}{L_0} \approx \gamma$$

Strains are almost always small so it can be assumed that  $\tan(\gamma) = \gamma$ .

Finally, a hydrostatic pressure causes an element of volume  $V$  to change in volume by  $\delta V = V - V_0$ . The **volumetric strain** or **dilatation**, is

$$\Delta = \frac{\delta V}{V}$$

Within the linear elastic regime, strain is proportional to stress. This holds for all three types of strain and stress mentioned above. The three relations are

$$\sigma = E\varepsilon$$

$$\tau = G\gamma$$

$$p = K\Delta$$

in which E, G and K are constants of proportionality, respectively called the **Young's modulus**, **shear modulus** and **bulk modulus**.

When stretched in one direction, a element generally contracts in the other two directions. **Poisson's ratio**  $\nu$  is the negative of the ratio of the lateral or transverse strain to the axial strain in tensile loading.

$$\nu = -\frac{\varepsilon_t}{\varepsilon}$$

Since the transverse strain itself is negative,  $\nu$  is positive. In an **isotropic material** (one for which the moduli do not depend on the direction in which the load is applied) the moduli are related in the following ways:

$$G = \frac{E}{2(1+\nu)} ; K = \frac{E}{3(1-2\nu)}$$

Commonly  $\nu \approx 1/3$  so that

$$G = \frac{3}{8}E ; K = E$$

except for elastomers, for which  $\nu \approx 1/2$  so that

$$G = \frac{1}{3}E ; K \gg E$$

Suppose a cubic element is subjected to three unequal stresses in three different direction (normal to each other). Using the formula for stress on the top of this page for the stress in one direction, then using poisson's ratio for the stresses in the other two directions and ultimately repeating this for the other stresses and summing the strains, gives us **Hooke's Law in three dimensions**

$$\varepsilon_1 = \frac{1}{E}(\sigma_1 - \nu\sigma_2 - \nu\sigma_3)$$

$$\varepsilon_2 = \frac{1}{E}(-\nu\sigma_1 + \sigma_2 - \nu\sigma_3)$$

$$\varepsilon_3 = \frac{1}{E}(-\nu\sigma_1 - \nu\sigma_2 + \sigma_3)$$

If a cube is constrained in a slot, it behaves like a material with an 'effective modulus' which is greater than E

$$\frac{\sigma_1}{\varepsilon_1} = \frac{E}{1-\nu^2}$$

This effect becomes more marked when there are constraints in more directions.

If you stretch an elastic band, **elastic energy** is stored in it. A force acting through a displacement  $dL$  does work  $F \cdot dL$ . A stress  $F/A$  acting through a strain increment  $d\varepsilon = dL/L$  does work per unit volume

$$dW = \frac{F dL}{AL} = \sigma d\varepsilon$$

with units of  $J/m^3$ . The work done per unit volume as the stress is raised from zero to a final value  $\sigma^*$  is the area under the stress-strain curve

$$W = \int_0^{\sigma^*} \sigma d\varepsilon = \int_0^{\sigma^*} \frac{\sigma d\sigma}{E} = \frac{(\sigma^*)^2}{2E}$$

The energy is released when the stress is relaxed.

Strain can be induced by stress fields, thermal fields, electric fields or magnetic fields.

### 4.3 The big picture: material property charts

Two examples of material property charts are the **modulus-density chart** and the **modulus-relative cost chart**.


Glasses and most polymers have disordered structures with no particular directionality about the way the atoms are arranged. They have properties that are **isotropic**, meaning they are the same no matter which direction they are measured. Most materials are **crystalline**: made up of ordered arrays of atoms. Metals and ceramics are usually **polycrystalline**: made up of many tiny, randomly oriented crystals. This averages out the directionality in properties. Anisotropy is important though, in single crystals, drawn polymers, fibres and woods.

### 4.4 The science: what determines stiffness and density


The atoms of a metal can be packed in many ways, three of which will be discussed here. They can be seen in figure 1. The CPH-structure has a ABAB... sequence, the third layer is exactly above the first layer, and so on. The FCC-structure has the same packing fraction, but has a ABCABC... sequence. The BCC-structure, which has a lower packing fraction than the two previous structures, consists of atoms packed in squares in an ABAB... sequence.

The characterising unit of a crystal structure is called its **unit cell**. Unit cells pack or fill space, the resulting array is called the **crystal lattice**. The points at which cell edges meet are called **lattice points**. The crystal itself is generated by attaching one or a group of atoms to each lattice point so that they form a regular, three-dimensional, repeating pattern.

Close-packed hexagonal structure CPH



Face-centred cubic structure FCC



Body-centred cubic structure BCC




figure 1

Ceramics can have the same ways of packing as metals, with different atoms at different spots. Glasses can be crystalline and amorphous, depending on the ring size.

Polymers can occur in many forms. Four of the most important ones are shown in figure 2. Polymers of type A only have weak hydrogen bonds. It is an amorphous **thermoplastic**. These weak bonds, however, try to keep the bond lengths short by lining the molecules up, resulting in polymers of type B, which are partly crystalline **crystallites**. **Elastomers** are polymers of type C, which have very few crosslinks. **Thermosets** are polymers of type D, which have a lot of crosslinks.

The **cohesive energy** measures the strength of the atomic bonds. It is defined as the energy per mol required to separate the atoms of a solid completely. The atoms have equilibrium spacing  $a_0$ , and a force can pull them apart a little, to  $a_0 + \delta$ . The stiffness then is

$$S = \frac{F}{\delta}$$

Relating this to the Young's modulus can be done as follows

$$\sigma = \frac{S}{a_0} \epsilon$$

$$E = \frac{S}{a_0}$$

The bonds between the molecules of an elastomer are weak, so weak that they have melted at room temperature. Segments are free to slide over each other, only limited by the few cross-links. This explains their very low stiffness. The modulus of elastomers increases with temperature, in contrast to the behaviour of all other solids.




figure 2

The temperature at which the weak inter-chain bonds of polymers start to melt is called the **glass transition temperature  $T_g$** . Elastomers and thermosets have a glass transition, but they decompose and burn instead of melt because of the cross-linking. Below  $T_g$ , thermoplastics are controlled by hydrogen bonds and referred to as 'glassy'. Above  $T_g$ , amorphous thermoplastics turn into a viscous flow. The degree of crystallinity determines how stiff the material remains above  $T_g$ , but eventually all thermoplastics melt and flow. The more a thermoset is cross-linked, the less it shows a glass transition. The glass transition temperature is sensitive to the deformation rate (how fast the material is deformed).

The density of a material is mainly determined by the atomic weight and only to a lesser degree by the atom size and the way in which they are packed.

The density of a metallic alloy can be determined using the **rule of mixtures**

$$\rho_{alloy} = f\rho_A + (1 - f)\rho_B$$

where  $f$  is the volume fraction of A atoms.

## 4.5 Manipulating the modulus and density

Composites are made by embedding fibres or particles (possible in many ways, see figure 3) in a continuous matrix of a polymer (PMC's), a metal (MMC's) or a ceramic (CMC's).




figure 3

The density of a composite, provided that it is a composite with no residual porosity, can be calculated as follows (the matrix and reinforcement are respectively denoted by the subscripts  $m$  and  $r$  and  $f$  is the volume fraction of the reinforcement)

$$\rho_{composite} = f\rho_r + (1 - f)\rho_m$$

The modulus of a composite is bracketed by two bounds. The upper bound,  $E_U$ , is found by assuming that on loading the two components strain by the same amount, like springs in parallel

$$E_{U, composite} = fE_r + (1 - f)E_m$$

The lower bound,  $E_L$ , can be found by assuming that the two components carry the same stress, like springs in series.

$$E_{L, composite} = \frac{E_m E_r}{fE_m + (1-f)E_r}$$




figure 4

Figure 4 shows an idealised cell of a low-density foam. It consists of solid cell walls or edges surrounding a void containing a gas.

$$\frac{\rho_{foam}}{\rho_{solid}} = \left(\frac{t}{L}\right)^2$$

$$\frac{E_{foam}}{E_{solid}} = \left(\frac{\rho_{foam}}{\rho_{solid}}\right)^2$$

## 4.6 Acoustic properties

**Sound** is transmitted through materials as an elastic wave. The **wavelength**  $\lambda$  is related to the **frequency**  $f$  by

$$f = \frac{v}{\lambda}$$

where  $v$  is the velocity of sound in the medium in which it is travelling. The longitudinal sound velocity in a long rod of a solid material, such that the thickness is small compared with the wavelength, is

$$v_1 = \sqrt{\frac{E}{\rho}}$$

If the thickness of the rod is large compared with the wavelength, the velocity, instead, is

$$v_B = \sqrt{\frac{E(1-\nu)}{(1-\nu-2\nu^2)\rho}}$$

Elastically anisotropic solids have sound velocities which depend on direction

$$\frac{v_{\parallel}}{v_{\perp}} = \sqrt{\frac{E_{\parallel}}{E_{\perp}}}$$

Sound power, even for very loud noise, is small. The proportion of sound absorbed by a surface is called the **sound-absorption coefficient**. The degree of insulation (keeping sound from outside, outside) is proportion to the mass of the wall, floor or roof through which sound has to pass. This is known as the **mass-law**.

If a sound-transmitting material is interfaced with a second one with different properties, part of the amplitude of the sound wave is transmitted across the interface and part is reflected back into the first material. This is determined by the **sound wave impedance**

$$Z = \sqrt{\rho E}$$

The **reflection coefficient R** is the fraction of the acoustic energy that is reflected, given

$$R = \left(\frac{Z_2 - Z_1}{Z_2 + Z_1}\right)^2$$

where  $Z_1$  is the impedance in the medium in which the sound originates and  $Z_2$  is that of the material into which it is transmitted. The energy that is not reflected is transmitted, so the **transmission coefficient T** is

$$T = 1 - R = \frac{4Z_1 Z_2}{(Z_2 + Z_1)^2}$$

The intensity of **sound radiation I** scales with modulus and density as

$$I \propto \sqrt{\frac{E}{\rho^3}}$$

The factor in the right half of this proportion is called the **radiation factor**. When the material is elastically anisotropic,  $E$  is replaced by  $\bar{E} = \sqrt{E_{\parallel} E_{\perp}}$ .

## **Chapter 5**

*Flex, sag and wobble: stiffness-limited design*

## 5.1 Introduction and synopsis

Every loading on any real component can be decomposed into some combination of tension, compression, bending and torsion, so it makes sense to have a catalog of solutions regarding stiffness for the standard modes.

## 5.2 Standard solutions to elastic problems

The relation between the load  $F$  and deflection  $\delta$  can be obtained using formulas for stress and strain from chapter 4

$$\delta = \frac{L_0 F}{AE}$$

The stiffness  $S$  for a tie loaded in tension is defined as

$$S = \frac{F}{\delta} = \frac{AE}{L_0}$$

When a beam is loaded by a bending moment  $M$ , its initially straight axis is deformed to a curvature  $\kappa$

$$\kappa = \frac{d^2 u}{dx^2} = \frac{1}{R}$$

where  $u$  is the displacement parallel to the  $y$ -axis. The stress differs with position  $y$ , so that

$$\frac{\sigma}{y} = \frac{M}{I} = E\kappa = E \frac{d^2 u}{dx^2}$$

where  $I$  is the second moment of area. The distance  $y$  is measured vertically from the neutral axis (position where the stress is zero). The ratio of moment to curvature is called the **flexural rigidity**. For a beam of length  $L$  with a transverse load  $F$ , the stiffness is

$$S = \frac{F}{\delta} = \frac{C_1 EI}{L^3}$$

$C_1$  depends on the load type, see figure 5.


A torque,  $T$ , applied to the ends of an isotropic bar of a uniform section generates a shear stress. For circular section, the shear stress varies with radial distance  $r$  from the axis of symmetry is

$$\frac{\tau}{r} = \frac{T}{K}$$

where  $K$  measures the resistance of the section to twisting (the torsional equivalent to  $I$ , for bending).  $K$  is equal to the polar second moment of area for circular sections. For non-circular sections,  $K$  is less than  $J$ . The shear stress causes the bar to twist through an angle  $\theta$ . It is related to the length, shear stress and torque by

$$\frac{\tau}{r} = \frac{T}{K} = \frac{G\theta}{L}$$

The ratio of torque to twist is called the **torsional rigidity**.



If sufficiently slender, an elastic column or plate, loaded in compression, fails by elastic buckling at a critical load

$$F_{crit} = \frac{n^2 \pi^2 EI}{L^2}$$

where  $n$  is a constant that depends on the end constraints (see figure 6). It is the number of half-wavelengths of the buckled shape.

Any undamped system vibrating at one of its natural frequencies can be reduced to the simple problem of a mass attached to a spring, having a lowest **natural frequency**

$$f = \frac{1}{2\pi} \sqrt{\frac{k}{m}}$$

The lowest natural frequencies of the flexural modes of uniform beams or plates can be calculated as follows, noticing that the spring stiffness is in this case equal to the stiffness  $S$

$$f = \frac{C_2}{2\pi} \sqrt{\frac{EI}{m_o L^4}}$$

where  $m_o$  is the mass of the beam per unit length: Ap.  $C_2$ -values can be seen in figure 5. The natural frequency becomes

$$f = \frac{C_2}{2\pi} \sqrt{\frac{I}{AL^4}} \sqrt{\frac{E}{\rho}}$$

Thus frequencies scale as  $\sqrt{E/\rho}$ .

figure 5




figure 6

### 5.3 Material indices for elastic design

The third step in choosing a material, ranking, is done based on **material indices**.

*Minimising weight: a light, stiff tie-rod*

The mass is to be minimised, so the **objective function** is

$$m = AL_0Q$$

Using the equation for stiffness for a tie and eliminating the area of the cross-section, we obtain

$$m = S^* L_0^2 \left( \frac{\rho}{E} \right)$$

with the required stiffness  $S^*$ . Both  $S^*$  and  $L_0$  are specified, so minimum mass occurs at maximum stiffness over density. We define the material index  $M_t$  (subscript 't' for tie) as

$$M_t = \frac{E}{\rho}$$

It is called the **specific stiffness**. Materials with a high value of  $M_t$  are, in this case, the best choice.

*Minimising weight: a light, stiff panel*

The objective function for a panel is

$$m = ALQ = bhLQ$$

We can use the same method as for a tie, instead using the formula for the stiffness for a bending beam, and the formula for the second moment of area for a rectangular section.

Eliminating h yields

$$m = \left(\frac{12S^*}{C_1 b}\right)^{1/3} (bL^2) \left(\frac{Q}{E^{1/3}}\right)$$

Again, the quantities  $S^*$ ,  $L$ ,  $b$  and  $C_1$  are all specified, the only freedom of choice left is that of the material. Minimum mass occurs at maximum values of  $E^{1/3}/\rho$ . The material index  $M_p$  for the panel is

$$M_p = \frac{E^{1/3}}{\rho}$$

*Minimising weight: a light, stiff beam*

The objective function for the mass of a square section beam is

$$m = b^2 LQ$$

Now using again the formula for the stiffness of a bending beam, but using the formula for the second moment of area of a square section beam instead of a rectangular section, we get, eliminating b,

$$m = \left(\frac{12S^* L^3}{C_1}\right)^{1/2} (L) \left(\frac{Q}{E^{1/2}}\right)$$

$S^*$ ,  $L$  and  $C_1$  are specified, so the material index  $M_b$  for a beam is

$$M_b = \frac{E^{1/2}}{\rho}$$

A rectangular beam does not have the optimum geometry in order to minimise weight. Shaping the cross-section enables an increase in the value of  $I$ , without changing  $A$ . We therefore introduce the **shape factor  $\Phi$** , defined as the ratio of  $I$  for the shaped section to that for a solid square section with the same area  $A$

$$\Phi = \frac{I}{I_{square}} = \frac{12I}{A^2}$$

The deeper and more thin-walled the cross-sectional shape, the larger the value of the shape factor, but there is a limit: make it too thin and the walls will buckle. Moreover, manufacturing limits the maximum achievable thinness. If we fill in the formula for the shape factor in the objective function for the beam, and then eliminate  $A$ , we obtain a different resulting performance index

$$M_b = \frac{(\Phi E)^{1/2}}{\rho}$$

*Minimising material cost*

If the material price is  $C_m$  \$/kg, the cost of the material to make the component is just  $mC_m$ . The objective function for the material cost  $C$  of the tie, panel or beam then becomes

$$C = mC_m = ALC_mQ$$

Proceeding as in the three previous examples then leads to indices that are the same, with  $\rho$  replaced by  $C_m\rho$ .

## 5.4 Plotting limits and indices on charts

If we take the logs of the material indices for a tie, beam and panel we respectively obtain

$$\log(E) = \log(Q) + \log(C)$$

$$\log(E) = 2\log(Q) + \log(C)$$

$$\log(E) = 3\log(Q) + \log(C)$$

with  $C$  being a constant. These lines one can plot in the  $E$ - $\rho$  charts. We refer to these lines as **selection guidelines**.

The methods for selecting materials shown above are practical when there are very few constraint. If there are a lot of factors that are variable, material selection is usually done using computers.

## 5.5 Case studies

The deflection  $\delta$  that can be seen in figure 4 can be calculated using the following formulas

$$\delta = \frac{FL^3}{C_1 E_{solid} I}$$

$$I = \frac{t^4}{12}$$

If one redesign something the natural frequencies of that component change. The change in frequency depends on the modulus and density of the new and old material

$$\Delta f = \sqrt{\frac{E_{new} \rho_{old}}{E_{old} \rho_{old}}}$$

## **Chapter 6**

*Beyond elasticity: plasticity, yielding and ductility*

## 6.1 Introduction and synopsis

The **yield stress** is the stress beyond which a material becomes plastic.

## 6.2 Strength, plastic work and ductility: definition and measurement

The **yield strength**  $\sigma_y$  (or **elastic limit**  $\sigma_{el}$ ) is, for metals, not always clearly determinable. We therefore identify  $\sigma_y$  with the 0.2% **proof stress**, that is, the stress at which the stress-strain curve for axial loading deviates by a strain of 0.2% from the linear elastic line. When strained beyond the yield point, most metals **work harden**, causing the rising part of the curve, until a maximum, the **tensile strength**  $\sigma_{ts}$ . This is followed in tension by non-uniform deformation (**necking**) and fracture. For polymers  $\sigma_y$  is identified as the stress at which the stress-strain curve becomes markedly non-linear: typically a strain of 1%. The behaviour beyond yield depends on the temperature relative to glass temperature  $T_g$ . Well below  $T_g$  most polymers are brittle. As  $T_g$  is approached, plasticity becomes possible until, at about  $T_g$ , thermoplastics exhibit **cold drawing**: large plastic extension at almost constant stress during which the molecules are pulled into alignment with the direction of straining, followed by hardening and fracture when alignment is complete. At still higher temperatures, thermoplastics become viscous and can be moulded, thermosets become rubbery and finally decompose.

**Plastic strain**,  $\epsilon_{pl}$ , is the permanent strain resulting from plasticity

$$\epsilon_{pl} = \epsilon_{tot} - \frac{\sigma}{E}$$

The **ductility** is a measure of how much plastic strain a material can tolerate. It is measured in standard tensile tests by the **elongation**  $\epsilon_f$  (the tensile strain at break) expressed as a percentage. Beyond the elastic limit **plastic work** is done in deforming a material permanently by yield or crushing. The plastic work per unit volume at fracture is

$$W_{pl} = \int_0^{\epsilon_f} \sigma d\epsilon_{pl}$$

which is just the area under the stress-strain curve.

Ceramics and glasses are brittle at room temperature. They do have yield strengths, but these are so enormously high that they are never reached, the material fractures first. The measure used for ceramics and glasses is the **compressive crushing strength**. We call it the **elastic limit** and give it the symbol  $\sigma_{el}$ , since it is not true yield even though it is the end of the elastic part.

A **hardness** test can be used instead of tensile and compression tests. Hardness is the load  $F$  divided by the area  $A$  of the indent, made by the instrument, projected onto a plane

perpendicular to the load. A commonly used scale, that of **Vickers**, uses units of kg/mm<sup>2</sup>, with the result that

$$H_v \approx \frac{\sigma_y}{3}$$

A hardness test is non-destructive, but less accurate.

Until now we have only considered **nominal stresses and strains**. However with stresses, dimensions change, and therefore also the stresses and strains. The formulas for **true stress and true strain** are, respectively

$$\sigma_t = \sigma_n(1 + \epsilon_n)$$

$$\epsilon_t = \int_{L_0}^L \frac{dL}{L} = \ln(1 + \epsilon_n)$$

For the elastic regime and small plastic strains, the difference between nominal and true stresses and strains is negligible.

### 6.3 The big picture: charts for yield strength

Strength can be displayed on material property charts. Two are particularly useful: the **strength-density chart** and the **modulus-strength chart**. For strength the yield strength or the elastic limit is used.

### 6.4 Drilling down: the origins of strength and ductility

The distance over which inter-atomic forces act is small: a bond is broken if it is stretched to more than about 10% of its original length. So the force needed to break bond is roughly

$$F = \frac{Sa_0}{10}$$

On this basis the **ideal strength** of a solid should therefore be roughly

$$\sigma_{ideal} = \frac{E}{10}$$

More refined calculations give a ratio of 1/15.

Crystals contain imperfections of several kinds, which can be seen in figure 7.

At the top left are **point defects**. All crystals contain **vacancies**: sites at which an atom is missing. At the top right a **substitutional solid solution** (the dissolved atoms replace those of the host) and a **interstitial solid solution** (the dissolved atoms squeeze into the spaces between the host atoms) are shown. Both are caused by the creation of **alloys**: a material in which a second element is dissolved. The different size of the atoms causes distortion in the surrounding lattice. Bottom left a **dislocation** is displayed. It is dislocations that make metals soft and ductile.




figure 7

The bottom right image shows a more drastic defect: **grain boundaries**. Here three perfect, but differently oriented, crystals meet. The individual crystals are called **grains**, the meeting surfaces are grain boundaries.

A dislocation can be done in two ways. An **edge dislocation** is made by sliding the top part of the crystal across the bottom (made possible by a cut) by one full atom spacing, and then reattaching the atoms. In this way the dislocation can 'travel' through the entire crystal. By the end of the process the upper part has slipped by the **slip vector  $\mathbf{b}$** . The result is shear strain. The upper part of the can also be displaced parallel to the edge of the cut (rather than normal to it). This creates a **screw dislocation**. All dislocation are either an edge or a screw dislocation, or a mix. In real crystals it is easier to make and move dislocations on some planes than on others. The preferred planes are called **slip planes**, the preferred directions **slip directions**.

Crystals resist the motion of dislocations with a friction-like resistance  $f$  per unit length. For yielding to take place the external stress must overcome  $f$ . The force does work

$$W = \tau L_1 L_2 b$$

$L_1$  and  $L_2$  being the dimensions of the plane the shear stress acts on and  $b$  being the magnitude of the slip vector. Equating this to the work done by the applied stress gives

$$\tau b = f$$

The atoms near the core of a dislocation are displaced from their proper positions, and thus they have higher potential energy. To keep the potential energy of the crystal as low as possible, the dislocation tries to be as short as possible: it behaves as if it had a **line tension**  $T$

$$T = \frac{1}{2} E b^2$$

The resistance to slip  $f$  comes from several factors. First is the **lattice resistance**  $f_i$ : the intrinsic resistance of the crystal structure to plastic shear. If this resistance is low, as in metals, the material can be strengthened by introducing obstacles to slip. This is done by adding alloying elements to give **solid solution hardening**  $f_{ss}$ , precipitates or dispersed particles giving **precipitation hardening**  $f_{ppt}$ , other dislocations giving what is called **work hardening**  $f_{wh}$  or grain boundaries introducing **grain-size hardening**  $f_{gb}$ .

Polymers with higher glass temperatures do not **draw** (see section 6.2 for cold drawing) at room temperature. They **craze** instead. Small crack-shaped regions within the polymer draw down. Because the crack has a larger volume than the polymer that was there to start with, the drawn material ends up as ligaments that link the craze surfaces. Crazes scatter light, so their presence causes whitening. Crazing limits ductility in tension.

## 6.5 Manipulating strength

**Spacing** means the distance  $L$  between obstacles that contribute to the resistance  $f$  in the slip plane.  $\alpha$  is a dimensionless constant characterizing obstacle strength.

If we roughen the slip plane by solid solution hardening, we add an additional resistance. The concentration of solute atoms is on average

$$c = \frac{b^2}{L^2}$$

The contribution to the shear stress required to move the dislocation then is

$$\tau_{ss} = \alpha E c^{1/2}$$

For precipitation-hardened materials the formula is

$$\tau_{ppt} = \frac{2T}{bL} = \frac{Eb}{L}$$

The **dislocation density** is defined as the length of dislocation line per unit volume. The contribution of the work hardening then is

$$\tau_{wh} = \frac{Eb}{2} \sqrt{\rho_d}$$

The contribution of grain boundary hardening depends on the grain size  $D$  and the Petch constant:  $k_p$

$$\tau_{gb} = \frac{k_p}{\sqrt{D}}$$

To a first approximation the strengthening mechanisms add up, giving a shear yield strength

$$\tau_y = \tau_i + \tau_{ss} + \tau_{ppt} + \tau_{wh} + \tau_{gb}$$

This is the yield strength, to link this to the yield strength of a **polycrystalline material in tension** in tension, we need another formula.

$$\tau = \frac{F \sin \theta}{A / \cos \theta} = \sigma \sin \theta \cos \theta$$

$\theta$  being the angle of the normal of the plane of the shear stress, to the axis of tension.

For a sample that has many strains

$$\sigma_y = 3\tau_y$$

Polymers cannot be strengthened by the principles described above. They have to be blended, drawn, cross-linked or reinforced.

## **Chapter 7**

*Bend and crush: strength-limited design*

## 7.1 Introduction and synopsis

Strength-limited design, is design to avoid plastic collapse. We want to avoid yielding.

## 7.2 Standard solutions to plastic problems

For ties and columns it is easy. If the stress does not exceed the yield stress, the material will not yield.

For bending beam and panels, the maximum stress occurs at the greatest distance  $y_m$  from the neutral axis. The maximum stress the beam or panel can take before yielding is

$$\sigma_{max} = \frac{My_m}{I} = \frac{M}{Z_e}$$

$Z_e = I/y_m$  and is called the **elastic section modulus**. Small zones of plasticity appear if the maximum stress is slightly exceeded. As the moment increases further the plastic zones grow until they penetrate through the section of the beam, linking to form a **plastic hinge**. Further increase causes it to collapse. This failure moment  $M_f$  is found by integrating the moment caused by the constant stress distribution over the section

$$M_f = \int_{section} b(y)|y|\sigma_y dy = Z_p \sigma_y$$

$Z_p$  being the **plastic section modulus**.

Failure in a shaft occurs when the maximum surface stress exceeds the yield strength of the material. The maximum shear stress is at the surface and has the value

$$\tau_{max} = \frac{TR}{K}$$

The yield stress in shear,  $k$ , is half the tensile yield stress, so the maximum torque a shaft can carry before collapsing (for a circular section) is

$$T = \frac{2}{3}\pi R^3 k$$

Helical springs are a special case of torsional loading. If the spring has  $n$  turns of wire of shear modulus  $G$ , each of diameter  $d$ , wound to give a spring of radius  $R$ , the stiffness is

$$S = \frac{F}{u} = \frac{Gd^4}{64nR^3}$$

where  $F$  is the axial force applied to the spring and  $u$  its extension. The elastic extension is limited by the onset of plasticity. This occurs at the force

$$F_{crit} = \frac{\pi d^3 \sigma_y}{32R}$$

Spinning disks or rings (flywheels) store kinetic energy  $U$ . Centrifugal forces generate a radial tensile stress in the disk that reaches a maximum value. The disk yields when the maximum radial tensile exceeds the yield strength

$$U = \frac{\pi}{4} \rho t \omega^2 R^4$$

$$\sigma_{max} = 0.42 \rho \omega^2 R^2$$

Stresses can also occur at contact. Consider a sphere of radius  $R$  pressed against a flat surface with a load  $F$ . Both sphere and surface have Young's modulus, Poisson's ratio is  $\frac{1}{3}$ . The radius of the contact area is

$$a \approx 0.7 \left( \frac{FR}{E} \right)^{1/3}$$

The relative displacement of the two bodies is

$$u \approx - \left( \frac{F^2}{E^2 R} \right)^{1/3}$$

Yielding first occurs due to shear stress, so

$$\tau_{max} = \frac{F}{2\pi a^2}$$

If this exceeds the shear yield strength  $k = \sigma_y/2$ , a plastic zone appears beneath the center of the contact.

Holes, slots, threads and changes in section concentrate the stress locally. We define the nominal stress in a component as the load divided by the cross-section. The **maximum local stress** is then found approximately by multiplying the nominal stress by a **stress concentration factor  $K_{sc}$**

$$K_{sc} = \frac{\sigma_{max}}{\sigma_{nom}} = 1 + \alpha \left( \frac{c}{\rho_{sc}} \right)^{1/2}$$

Here  $\rho_{sc}$  is the minimum radius of curvature of the stress-concentrating feature and  $c$  is a characteristic dimension associated with it: either the half-thickness of the remaining ligament, the half-length of a contained notch, the length of an edge notch or the height of a shoulder. The factor  $\alpha$  is roughly 2 for tension,  $\frac{1}{2}$  for torsion and bending.

## 7.3 Material indices for yield-limited design

*Minimising weight: a light, strong tie-rod*

We want to minimise weight, and therefore minimise mass

$$m = AL\rho$$

In order to carry the load  $F$  without yielding

$$\frac{F}{A} \leq \sigma_y \rightarrow m \geq FL \left( \frac{\rho}{\sigma_y} \right)$$

The lightest tie that will carry  $F$  safely is that made of the material with the smallest value of  $\rho/\sigma_y$ . As in Chapter 5, defining a material index

$$M_t = \frac{\sigma_y}{\rho}$$

*Minimising weight: light, strong panels*

We can apply more or less the same method as in Chapter 5 for elastic design. We come to

$$M_p = \frac{\sigma_y^{1/2}}{\rho}$$

*Light, strong beams: the effect of shape*

The analysis for a beam is similar to that of the panel. The resulting material index is

$$M_b = \frac{\sigma_y^{2/3}}{\rho}$$

The factor for strength is

$$\Phi_B^y = \frac{Z_e^{shaped}}{Z_e^{solid}}$$

Minimising material cost or volume for strength design works the same as for stiffness design.

## 7.4 Case studies

When a ligament of thickness  $t$  is bent elastically to a radius  $R$ , the surface strain is

$$\varepsilon = \frac{t}{2R}$$

## **Chapter 8**

### *Fracture and fracture toughness*

## 8.1 Introduction and synopsis

**Toughness** is the resistance to fracture. It requires a new material property, the **fracture toughness**.

## 8.2 Strength and toughness

If one had to design a test to characterise toughness, one would notch it, yank it or whack it till it breaks, measuring the energy to do so. These test though, do not measure a true material property. They are solely used to the purpose of ranking.

## 8.3 The mechanics of fracture

Cracks and notches concentrate stress. The local stress at a distance  $r$  from the tip of a crack, caused by a remote uniform tensile stress is

$$\sigma_{local} = \sigma \left( 1 + Y \sqrt{\frac{\pi c}{2\pi r}} \right)$$

where  $Y$  is a constant with a value near unity that depends weakly on the geometry of the cracked body. Far from the crack, where  $r \gg c$ , the local stress falls to the value  $\sigma$ , near the tip, where  $r \ll c$ , it rises steeply as

$$\sigma_{local} = Y \frac{\sigma \sqrt{\pi c}}{\sqrt{2\pi r}}$$

So for any given value of  $r$  the local stress scales as  $\sigma \sqrt{\pi c}$ , which therefore is a measure of the 'intensity' of the local stress field. This quantity is called the **mode 1 stress intensity factor  $K_1$**  (the 'mode 1' means tensile loading perpendicular to the crack

$$K_1 = Y \sigma \sqrt{\pi c}$$

The loading on the crack tip region that drives potential failure is an elastic stress field that scales with  $K_1$ . As a result cracks propagate when the stress intensity factor exceeds a critical value, the **fracture toughness  $K_{1c}$**

$$K_{1c} = K_1 = Y \sigma^* \sqrt{\pi c} \approx \sigma^* \sqrt{\pi c}$$

It is a material property, so the value is independent of the way it is measured. Important applications of this formula are calculating the failure stress or the critical crack length.

When a sample fractures, a new surface is created. Surfaces have energy, the **surface energy  $\gamma$** . If you fracture a sample across a cross-section area  $A$  you make an area  $2A$  of new surface, requiring an energy of at least  $2A\gamma$  joules to do so. Consider first the question of the **necessary condition for fracture**. It is that sufficient external work be done, or elastic energy released, to at least supply the surface energy of the new surfaces that are created

$$G \geq 2\gamma$$

where  $G$  is called the **energy release rate**. Growing a crack costs energy  $G_c$ .  $G_c$  is called, confusingly, the **toughness** or the **critical strain energy release rate**. A slab of material of unit thickness carrying a stress has elastic energy

$$U_v = \frac{\sigma^2}{2E}$$

If we put a crack in it, it releases the stress in a half-cylinder of radius about  $c$  releasing the energy it contained

$$U(c) = \frac{\sigma^2 \pi c^2}{4E}$$

Suppose now that the crack extends by  $\delta c$ . The condition for fracture becomes

$$\delta U = \frac{\sigma^2 \pi c}{2E} \delta c = G_c \delta c$$

$$\frac{K_{1c}^2}{2E} = G_c$$

This derivative is an approximate one. The correct result we want is

$$K_{1c} = \sqrt{E G_c}$$

$G_c$  is also a material property.

The intense stress field at the tip of a crack generates a **process zone**: a plastic zone in ductile solids, a zone of micro-cracking in ceramics, a zone of delamination, debonding and fibre pull-out in composites. The radius of the plastic zone, allowing for stress redistribution is

$$r_y = 2 \left( \frac{\sigma^2 \pi c}{2\pi \sigma_y^2} \right) = \frac{K_1^2}{\pi \sigma_y^2}$$

When cracks are small, materials yield before they fracture, when they are large, the opposite is true. Above the critical crack length materials fracture, below they yield

$$c_{crit} = \frac{K_{1c}^2}{\pi \sigma_y^2}$$

The stress at which the material fractures is

$$\sigma_f = \frac{K_{1c}}{\pi \sigma_y^2}$$

## 8.4 Material property charts for toughness

Fracture toughness can be plotted in two charts. In the **fracture toughness-modulus chart**, the toughness  $G_c$  is incorporated using straight lines. In the **fracture toughness-strength** the transition crack length can be incorporated in the same way.

## 8.5 Drilling down: the origins of toughness

An energy of at least  $2\gamma$  is needed to cut a material. The atoms are bonded on all sides so the surface atoms lose one-sixth of their bonds when the cut is made. This means that we have to provide one-sixth of the cohesive energy  $H_c$  to a slice  $4r_0$  thick, where  $r_0$  is the atom radius. So the surface energy should be

$$\gamma = \frac{1}{3}H_c r_0$$

$H_c$  is typically  $3 \times 10^{10} \text{ J/m}^3$  and  $r_0$   $10^{10} \text{ m}$ .  $G_c$  is often way larger than  $2\gamma$ , the extra energy is going into plastic work.

Brittle fracture is characteristic of ceramics and glasses. They have very high yield strengths, giving them no way to relieve the crack tip stresses by plastic flow. This means that, near the tip, the stress reaches the ideal strength, which is enough to tear the atomic bonds apart, allowing the crack to grow and accelerate until it reaches the speed of sound.

Ductile materials have inclusions. As the material is stretched, it deforms at first in a uniform way, building up stress at the inclusions, which act as stress concentrations. These either separate from the matrix or fracture, nucleating tiny holes. The holes grow as strain increases, linking and weakening the part of the specimen in which they are most numerous until they finally coalesce to give a **ductile fracture**. Polymers do the same, except they do not have inclusions, but they craze.

Most materials have yield strengths that increase as the temperature falls, with the result that the plastic zone at any crack they contain shrinks until it becomes so small that the fracture mode switches, giving a **ductile-to-brittle transition**.

Grain boundary segregation can create a network of low-toughness paths through the material so that, although the bulk of the grains is tough, the material as a whole fails by brittle intergranular fracture.

## 8.6 Compressive and tensile failure of ceramics

In tension, the 'worst flaw' (the crack with the biggest size and the most unfortunate orientation to stress) propagates to failure. In compression, the cracks can still extend, but in a stable manner. They grow parallel to the applied compression, and they only continue to extend if the stress is further increased. Eventually the extent of damage to the material is such that an overall sample instability occurs, with the material fragmenting into a band of crushed material that shears away.

The statistical distribution in flaw size and orientation leads to a probability of survival  $P_s$

$$P_s(V_0) = \exp\left\{-\left(\frac{\sigma}{\sigma_0}\right)^m\right\}$$

$\sigma_0$  is the reference stress for this volume, it is the stress at which there is a survival probability of  $1/e$ . This is called the **Weibull distribution**, with **Weibull modulus m**. The probability of survival can also be calculated for other volumes than  $V_0$

$$P_s(V) = (P_s(V_0))^{V/V_0} = \exp\left\{-\frac{V}{V_0}\left(\frac{\sigma}{\sigma_0}\right)^m\right\}$$

If the stress is not uniform, we need an integral form of the Weibull equation

$$P_s(V) = \exp\left\{-\frac{1}{V_0\sigma_0^m} \int_V \sigma^m dV\right\}$$

Maximum bending stress can be compared with a tensile stress

$$\frac{\sigma_b}{\sigma_t} = (2(m+1))^{1/m}$$

## 8.7 Manipulating properties: the strength-toughness trade-off

It is not easy to make materials that are both strong and tough. More often it is a trade-off between the two properties. Composites made of a brittle polymer and brittle fibers can still have a high fracture toughness, because there is frictional shear force between the fibers and the matrix. Also the stronger fibers can bridge the crack in the matrix. When the fibers do break, there are still ligaments of fiber buried in the matrix.

## **Chapter 9**

*Shake, rattle and roll: cyclic loading, damage and failure*

## 9.1 Introduction and synopsis

Materials grow tired if repeatedly stressed, with failure as a consequence. We call this **fatigue**.

## 9.2 Vibration and resonance: the damping coefficient

No material is perfect, some elastic energy is always lost in a load-unload cycle. The **mechanical loss coefficient** or **damping coefficient  $\eta$**  measures the degree to which a material dissipates vibrational energy.

## 9.3 Fatigue

Low-amplitude vibration causes no permanent damage in materials. Increase the amplitude, however, and the material starts to suffer fatigue. **Low-cycle fatigue** means that the component survives for only a small number of cycles, which is typical of cycling at stress above the yield stress. More interesting is **high-cycle fatigue**, where the stresses remain elastic. We distinguish **initiation-controlled fatigue** (no cracks at the beginning) and **propagation-controlled fatigue** (cracks at the beginning, or the assumption that cracks are present for safety reasons).

Most stress-tests use a sinusoidally varying stress with an amplitude of

$$\sigma_a = \frac{\Delta\sigma}{2} = \frac{\sigma_{max} - \sigma_{min}}{2}$$

This amplitude is present around a mean stress of

$$\sigma_m = \frac{\sigma_{max} + \sigma_{min}}{2}$$

Fatigue data are usually reported for a specified R-value

$$R = \frac{\sigma_{min}}{\sigma_{max}}$$

An R-value of -1 means that the mean stress is zero, an R-value of 0 means the stress cycles from 0 to maximum stress. For many materials there exists a **fatigue** or **endurance limit  $\sigma_e$** . It is the stress amplitude, about zero mean stress, below which fracture does not occur at all, or only after a very large number of cycles. Experiments show that the high-cycle fatigue life is approximately related to the stress range by what is called **Basquin's law**

$$\Delta\sigma N_f^b = C_1$$

where b and  $C_1$  are constant. The corresponding strain range then is

$$\Delta\varepsilon = \frac{\Delta\sigma}{E} = \frac{C_1}{EN_f^b}$$

In low-cycle fatigue the peak stress exceeds yield, so at least initially, the entire sample is plastic. We cannot use Basquin's law here, we instead use **Coffin's law**

$$\Delta \epsilon_{pl} = \frac{C_2}{N_f^c}$$

where  $\Delta \epsilon_{pl}$  means the plastic strain range,  $c$  and  $C_2$  again are constants.

These rules are for constant stress amplitudes. For variations we need other empirical laws.

**Goodman's rule** relates the stress range  $\Delta \sigma_{\sigma_m}$  for failure under a mean stress to that for failure at zero mean stress  $\Delta \sigma_{\sigma_0}$

$$\Delta \sigma_{\sigma_m} = \Delta \sigma_{\sigma_0} \left(1 - \frac{\sigma_m}{\sigma_{ts}}\right)$$

The variable amplitude problem can be addressed approximately with **Miner's rule of cumulative damage**. If  $N_1$  cycles are spent at a certain stress amplitude, a fraction  $N_1/N_{f1}$  of the available life is used up, where  $N_{f1}$  is the number of cycles to failure at that stress amplitude.

$$\sum_{i=1}^n \frac{N_i}{N_{f,i}} = 1$$

Fatigue crack growth is studied by cyclically loading specimens containing a sharp crack of length  $c$ . We define the cyclic stress intensity range as

$$\Delta K = K_{max} - K_{min} = \Delta \sigma \sqrt{\pi c}$$

The range increases with time under constant cyclic stress because the crack grows in length. The growth per cycle is  $dc/dN$ . The rate is zero below a threshold cyclic stress intensity  $\Delta K_{th}$ . Above it, there is a steady-state regime described by the **Paris law**

$$\frac{dc}{dN} = A \Delta K^m$$

where  $A$  and  $m$  are constants.

## 9.4 Charts for endurance limit

We can plot the endurance limit against the tensile strength in an **endurance limit-strength chart**, in which almost all materials appear to lie on the line  $\sigma_e = 0.33 \sigma_{ts}$ .

## 9.5 Drilling down: the origins of damping and fatigue

When the temperature is lower than the glass temperature, polymers provide relatively low damping, when the temperature is higher, the opposite is true.

Even though the general stress levels are below yield, the locally magnified stresses can lead to reversing plastic deformation. Dislocation motion is limited to a small volume near the

stress concentration, but that is enough to cause damage that finally develops into a tiny crack, which can propagate and cause failure.

## 9.6 Manipulating resistance to fatigue

The fatigue ratio is defined as

$$F_r = \frac{\sigma_e}{\sigma_y}$$

A material can be 'resistant' to fatigue by making sure they contain as few defects as possible, or providing a compressive surface stress, since cracks only propagate during the tensile part of a stress cycle.

## **Chapter 10**

*Keeping it all together: fracture-limited design*

## 10.1 Introduction and synopsis

The best choice of material often involves combinations of several material properties.

## 10.2 Standard solutions to fracture problems

Fracture can be avoided by manipulating the geometry and loads.

## 10.3 Material indices for fracture-safe design

In a **load-limited** design, the part will fail in a brittle way if the stress exceeds the critical value. To maximise the load we want materials with highest values of

$$M_1 = K_{1c}$$

The maximum energy a spring can store is

$$U_e^{max} = \frac{Y^2}{2\pi c} \left( \frac{K_{1c}^2}{E} \right)$$

Therefore the material index for **energy-limited** design is

$$M_2 = \frac{K_{1c}^2}{E} = G_c$$

The failure strain is

$$\epsilon_f = \frac{CK_{1c}}{E\sqrt{\pi c_{max}}}$$

The best materials for **displacement-limited** design are those with large values of

$$M_3 = \frac{K_{1c}}{E}$$

These three material indices can be plotted in the fracture toughness-modulus chart.

## 10.4 Case studies

If we have a **fail-safe design**, we want to be able to have a component that fails without catastrophic results.

Using the formula for maximum crack size for which the vessel will yield before break, we can define a material index for tolerable crack size and thus the integrity of the vessel

$$M_4 = \frac{K_{1c}}{\sigma_y}$$

If we want a leak before break condition, we get the following material index

$$M_5 = \frac{K_{1c}^2}{\sigma_y}$$

However we also want a wall that is reasonably thin, so we also seek a reasonably high value of

$$M_6 = \sigma_y$$

## **Chapter 12**

*Agitated atoms: materials and heat*

## 12.1 Introduction and synopsis

Thermal properties quantify the response of materials to heat.

## 12.2 Thermal properties: definition and measurement

Pure crystalline solids have a sharp **melting point**  $T_m$ , alloys usually melt over a temperature range. Non-crystalline molecular materials such as thermoplastics have a more gradual transition from true solid to very viscous liquid.

The **maximum service temperature**  $T_{max}$  tells us the highest temperature at which the material can be used continuously without oxidation, chemical change or excessive distortion becoming a problem. The **minimum service temperature**  $T_{min}$  is the temperature below which the material becomes brittle or otherwise unsafe to use.

The energy to heat 1 kg of material by 1 K is called the **heat capacity** or **specific heat**  $C_p$  ( $C_v$  for gases).

Most materials expand when they are heated. The thermal strain per degree of temperature change is measured by the **linear thermal expansion coefficient**  $\alpha$ . It is defined by

$$\alpha = \frac{dL}{LdT}$$

where L is a linear dimension of the body. If the material is anisotropic it expands differently in different directions.

The rate at which heat is conducted through a solid at steady-state (meaning that the temperature profile does not change with time) is measured by the **thermal conductivity**  $\lambda$ . It can be measured by recording the **heat flux**  $q$  flowing through the material from a surface at higher temperature  $T_1$  to a lower one at  $T_2$  separated by a distance  $x$ . **Fourier's law** is then

$$\lambda = - \frac{dT}{dx} = \lambda \frac{T_1 - T_2}{x}$$

The property governing transient heat flow (when temperature varies with time) is the **thermal diffusivity**,  $a$ . Diffusivity and conductivity are related by

$$a = \frac{\lambda}{\rho C_p}$$

## 12.3 The big picture: thermal property charts

We can plot the thermal conductivity against the thermal expansion, the yield strength or the thermal diffusivity. In the latter case, all solid materials lie on the line

$$\frac{\lambda}{a} = \rho C_p \approx 3 \times 10^6 \text{ J/m}^3 \cdot \text{K}$$

## 12.4 Drilling down: the physics of thermal properties

If a solid expands when heated it must be because the atoms are moving farther apart. The stiffer the 'springs' between atoms, the steeper is the force-displacement curve and the narrower is the energy well in which the atom sits, giving less scope for expansion. Thus, materials with high modulus, have low expansion coefficient and vice versa. A good approximation is

$$\alpha \approx \frac{1.6 \times 10^{-3}}{E}$$

All crystalline solids expand by about the same amount on heating from absolute zero to their melting point: it is about 2%

$$\alpha \approx \frac{0.02}{T_m}$$

Heat is transmitted through solids in three ways: by thermal vibrations, by the movement of free electrons in metals and, if they are transparent, by radiation. Transmission by thermal vibrations involves the propagation of **elastic waves**. When a solid is heated the heat enters as elastic wave packets or **phonons**. The phonons travel through the material and they move with the speed of sound  $c_0$  ( $= \sqrt{E/\rho}$ ). However these phonons scatter after an average distance which we call the **mean free path**  $l_m$  and this is why heat does not diffuse at the speed of sound.

We calculate the conductivity by using a **net flux model**, much as you would calculate the rate at which cars accumulate in a car park by counting the rate at which they enter and subtracting the rate at which they leave. Phonon conduction can be understood in a similar way. We find the thermal conductivity to be

$$\lambda = \frac{1}{3} \rho C_p l_m c_0$$

Elastic waves contribute little to the conductivity of pure metals because the heat is carried more rapidly by the free electrons. Free electrons also conduct electricity, with the result that metals with high electrical conductivity also have high thermal conductivity.

## 12.5 Manipulating thermal properties

The thermal conductivity can be lowered by introducing **scattering centres** such as impurity atoms or finely dispersed particles. Precipitation hardening and solution hardening cause a lower thermal conductivity, while work hardening does minimal change.

## 12.6 Design and manufacture: using thermal properties

**Differential thermal expansion** generates **thermal stress** if constrained. Imagine a thin film bonded onto a component that is much thicker than the film. If  $\alpha_{\text{film}} > \alpha_{\text{material}}$  the surface layer shrinks more than the substrate when cooled. If we want to stick the film back on the component, covering the same surface as before, we must stretch it by the strain

$$\varepsilon = \frac{\delta L_1 - \delta L_2}{L_0} = \Delta T(\alpha_1 - \alpha_2)$$

This requires a stress in the film of

$$\sigma_1 = \frac{E_1}{(1-\nu)} \Delta T(\alpha_1 - \alpha_2)$$

So if you join dissimilar materials you must expect thermal stress when they are heated or cooled. The way to avoid it is to avoid material combinations with very different expansion coefficients, or to grade the joint with one or more materials with expansion that lies between the two. Another is to put a compliant layer in between the materials.

Thermal expansion can also be used to **sense** (to measure temperature change) and to **actuate** (to open or close valves or electrical circuits, for instance).

Thermal expansion can lead to distortion in a single material too. A **temperature gradient** across a component will lead to differential thermal expansion. The solution is to make the equipment from material with low thermal expansion coefficient and high thermal conductivity.

Suppose a chunk of material is suddenly cooled by a change in temperature. The surface, almost immediately, adjusts to the temperature of the bath and it wants to contract by a strain. Since the surface is stuck to the interior, it is constrained, and thermal stresses appear. If the bulk of the interior does not strain at all, the stress induced is

$$\sigma = \frac{E}{(1-\nu)} \alpha \Delta T$$

In ductile materials, the stress can be sufficient to yield the interior, giving a final misfit in the strain and a state of **residual stress**, even after the whole component has cooled down. In brittle materials, the stress induced in a quenched material can cause fracture. The ability of a material to resist this, its **thermal shock resistance**  $\Delta T_s$ , is the maximum sudden change of temperature to which such a material can be subjected without damage.

If we have to solve a certain case, with the temperature changing everywhere continuously, we call it a **transient heat flow** problem. 1D heat flow is not sufficient, although it is a good approximation in many situations.

The variation in the amount of heat being transferred from point to point governs the rate of change of temperature at that location.

The best materials that conduct heat well and yet are strong, are those with the highest values of the index  $\lambda\sigma_y$ .

When materials vaporise, or melt, they absorb or release heat, the **latent heat L** of the phase change, without changing temperature.

## **Chapter 13**

*Running hot: using materials at high temperatures*

## 13.1 Introduction and synopsis

**Diffusion** is the movement of atoms through solids. **Creep** (and **creep fracture**) is the continuous deformation of materials under load at temperature.

## 13.2 The temperature dependence of material properties

Some properties depend on temperature T in a linear way, meaning that

$$P \approx P_0 \left( 1 + \beta \frac{T}{T_m} \right)$$

where P is the value of the property, P<sub>0</sub> its low-temperature value and β is a constant.

When a substance flows, its particles change neighbours, flow is a process of shear.

**Viscous flow** occurs at constant volume and this means that problems of viscous flow can be solved by taking the solution for elastic deformation and replacing the strain by the strain rate

$$\dot{\epsilon} = \frac{\sigma}{3\eta}$$

η being the viscosity.

At room temperature, most metals and ceramics deform in a way that depends on stress but not on time. As the temperature is raised, loads that are too small to give permanent deformation at room temperature cause materials to **creep**: to undergo slow, continuous deformation with time, ending in fracture.

The **initial elastic** and the **primary creep** strains occur quickly and can be treated in much the way that elastic deflection is allowed for in a structure. Thereafter, the strain increases steadily with time in what is called the **secondary creep** or the **steady-state creep** regime

$$\dot{\epsilon}_{SS} = B\sigma^n$$

where n is the **creep exponent**. It usually lies between 3 and 8 and for that reason this behaviour is called **power-law creep**. At low stress there is a tail with slope n≈1 (diffusional flow), in the log steady-state creep rate-log stress diagram. Steady-state creep rate can also be plotted against the temperature

$$\dot{\epsilon}_{SS} = C \cdot \exp - \left( \frac{Q_c}{RT} \right) = C' \sigma^n \cdot \exp - \left( \frac{Q_c}{RT} \right) = \dot{\epsilon}_0 \left( \frac{\sigma}{\sigma_0} \right)^n \cdot \exp - \left( \frac{Q_c}{RT} \right)$$

C, C',  $\dot{\epsilon}_0$ , σ<sub>0</sub>, n and Q<sub>c</sub> (the **activation energy for creep**) characterise the steady state creep of a material, they are essentially constants.

As creep continues, damage accumulates. It takes the form of voids or internal cracks that slowly expand and link, eating away the cross-section and causing the stress to rise. This makes the creep rate accelerate as shown in the tertiary stage of the creep curve. **Times to failure  $t_f$**  are normally presented as **creep-rupture diagrams**, if you know the stress and temperature you can read off the life.

### 13.3 Charts for creep behaviour

We have different types of diagrams, showing creep behaviour. First of all we have diagrams showing the melting point. Secondly we have the **strength-maximum service temperature** chart. Lastly we have the **creep strength at 950 °C-density** chart. This last chart can be used in exactly the same way as the yield strength-density chart, allowing likewise indices.

### 13.4 The science: diffusion

**Diffusion** is the spontaneous intermixing of atoms over time. In crystalline solids the atoms are confined to lattice sites, but in practice they can still move and mix, if they are warm enough. Crystals contain **vacancies**: occasional empty atom sites. These provide a way for diffusive jumps to take place. To make such a jump, an atom must break away from its original site, its **ground state**, and squeeze between neighbours, passing through an **activated state**, to drop into the vacant site where it falls back to its ground state again. There is an energy barrier  $q_m$ , between the ground state and the activated state to overcome if the atom is to move.  $q_d$  is called the **activation energy for self-diffusion**. If the 'jumping' atom is chemically different from its neighbours, we speak of **inter-diffusion**.

Picture a solid in which there is a **concentration gradient  $dc/dx$**  of atoms of type A across the solid. We have a plane in the middle of the solid. To the left are more atoms of type A, to the right of type B. If atoms jump across this plane at random, there will be a net flux of A atoms to the right because there are more on the left to jump, and a net flux of B atoms in opposite direction. The net flux of atoms of type A jumping to the right is defined in Fick's law as

$$J = -D \frac{dc}{dx}$$

$$D = D_0 \cdot \exp - \left( \frac{Q_d}{RT} \right)$$

where  $D$  and  $D_0$  are **diffusion coefficients** and  $Q_d$  is the activation energy per mole. Fick's law is only valid for a uniform concentration gradient.

A stress gradient can drive a diffusional flow as well. An electric field gradient can drive diffusion in non-conducting materials and even a temperature gradient can drive diffusion of matter.

## 13.5 The science: creep

In a polycrystalline material, the grain boundaries act as vacancies for atoms. The process is such, that certain faces of the grains are eaten away and others grow: if a vacancy joins a boundary (a source), an atom must leave it, if instead a vacancy leaves a boundary (a sink), an atom must join it.

Diffusion can unlock dislocations from obstacles in their path, making it easier for them to move.

Voids nucleate on grain boundaries that lie normal to the tensile stress. These voids act as sources for atoms and therefore they propagate to failure.

Materials can deform by dislocation plasticity, diffusional flow or power-law creep. If the stress and temperature are too low for any of these, the deformation is elastic. This competition between mechanisms is summarised in **deformation mechanism diagrams**.

Because most polymers are partly or wholly amorphous, diffusion is controlled by free volume. Near glass temperature, polymers are neither simple elastic solids nor viscous liquids: they are **visco-elastic solids**.

## 13.6 Materials to resist creep

The best way to avoid diffusional flow for metals and ceramics is to choose one with a high melting temperature and a large grain size, so that diffusion distances are long. Single crystals are best of all. Materials that best resist power-law creep are those with high melting points and a microstructure that maximises obstruction to dislocation motion.

Polymers that best resist creep are those with high glass temperatures (so high degree of cross-linking), high molecular weight (and therefore high viscosity) and a high degree of crystallinity.

## 13.7 Design to cope with creep

Creep problems are of four types:

- Those in which limited creep strain can be accepted but creep rupture must be avoided.
- Those in which creep strain is design limiting.
- Those involving more complex problems of creep strain, loss of stiffness and risk of buckling.
- Those involving stress relaxation.

## **Chapter 17**

*Durability: oxidation, corrosion, degradation*

## 17.1 Introduction and synopsis

**Durability** is a key material attribute, one central to the safety and economy of products, but it is also one of the more difficult attributes to characterise, quantify and use for selection for the following reasons:

- It is a function not just of the material but also of the environment in which it operates.
- There are many mechanisms, some general, some peculiar to particular materials and environments.
- Material combinations and configuration play a role.

## 17.2 Oxidation, flammability and photo-degradation

The most stable state of most elements is as an **oxide**. From the moment materials are made they start to re-oxidise, some extremely slowly, others more quickly. The hotter they are, the faster it happens.


If an oxide adheres to a material, the sample gains weight in a way that is either linear or parabolic in time  $t$ , if instead the oxide is volatile, the sample loses weight linearly with time.

There are several ways to characterise the **flammability** of a polymer. The most logical is the **Limiting oxygen index (LOI)**: it is the oxygen concentration required to maintain steady burning. Polymers with an oxygen index lower than 21% (that of air) will burn freely in air. A high oxygen index means resistance to self-sustained burning.

You don't have to set fire to a polymer for it to oxidise. Polymers and elastomers age when exposed to light (particularly UV) and oxygen, causing loss of strength, stiffness and toughness, discoloration and loss of gloss. This is countered by additives: **antioxidants**, **light stabilisers** and **fluorescent whitening agents**.

## 17.3 Oxidation mechanisms

The driving force for a metal to oxidise is its **free energy of oxidation**: the energy released when it reacts with oxygen. The rate of oxidation is determined by the **kinetics** of the oxidation reaction, and that has to do with the nature of the oxide. When any metal (with a few exceptions) is exposed to air, an ultra-thin surface film of oxide forms on it immediately, following the oxidation reaction



Some metals have porous or cracking oxide films, and their weight gain per unit area is linear, and this implies that the oxidation is progressing at a constant rate

$$\frac{d\Delta m}{dt} = k_l \rightarrow \Delta m = k_l t$$

$k_l$  being the **linear kinetic constant**. Other metals develop an oxide film on their surface that is compact, coherent and strongly bonded to the metal. For these metals the weight gain per unit area of surface is parabolic, slowing up with time, and this implies an oxidation rate with the form

$$\frac{d\Delta m}{dt} = \frac{k_p}{\Delta m} \rightarrow \Delta m^2 = k_p t$$

where  $k_p$  is the **parabolic kinetic constant**. The rate of growth of the film is proportional to the flux of atoms diffusing through the film. The most protective films are those with low diffusion coefficients, and this means that they have to have high melting points. If an oxide is volatile, it simply evaporates as it forms.

## 17.4 Resistance to oxidation, burning and photo-degradation

An oxide film can be artificially thickened by **anodising**: an electro-chemical process for increasing their protective power. Alloying helps resisting oxidation as well.

The combustion of a polymer is an exothermic reaction in which hydrocarbons are oxidised to carbon dioxide and water. The combustion is a **gas phase reaction**: the polymer or its decomposition products must become gaseous for a fire to begin. When you light a candle you are melting the wax and raising it to the temperature at which it **pyrolyses** forming gaseous hydrocarbon decomposition products. These gases react in the flame to produce heat. The heat of a fire of other combustible materials radiates out causing polymers to decompose into a flammable gas mix. **Flashover** occurs when these gases ignite. Combustion involves the reaction of **free-radicals**. The hydrogen radical reacts with oxygen and the hydrocarbon radical to give carbon dioxide and heat, releasing the hydrogen radical again to propagate the reaction further. The fire can be suppressed by **flame retardants** that either react with the radicals or create a protective layer of water vapor between the solid polymer and the gaseous decomposition products.

When exposed to radiation chemical reactions are triggered in the polymer that change their chemical composition and molecular weight, causing them to become brittle and change its optical properties. These reactions, called **photo-oxidation** or **photo-degradation**, also create free radicals.

## 17.5 Corrosion: acids, alkalis, water and organic solvents

Acids and alkalis attack almost all metals. Metals, ceramics and glasses are largely immune to them, but not all polymers can tolerate organic liquids without problems.

## 17.6 Drilling down: mechanisms of corrosion

Pure water dissociates a little to give a hydrogen ion and a hydroxyl ion. The product of the concentrations of the two ions is constant: increase one and the other falls. This is known as Law of Mass Action

$$[H^+] \cdot [OH^-] = constant$$

Where the square brackets mean 'molar concentration', the number of moles of an ion per liter of water. In pure water there are equal numbers of the two types of ion, and the value of the constant is  $10^{-14}$ . The pH of the ionised water is defined as the negative of the log of the hydrogen ion concentration

$$pH = -\log[H^+]$$

**Corrosion** is the degradation of a metal by an electro-chemical reaction with its environment. If a metal is placed in a conducting solution like salt water, it dissociates into ions, releasing electrons, via the anodic reaction (in this case for iron)



The electrons accumulate on the iron giving it a negative charge that grows until the electrostatic attraction starts to pull the positive iron-ions back onto the metal surface. At this point the iron has a potential (relative to a standard, the **hydrogen standard**) of -0.44 volts. Each metal has its own characteristic potential (called the **standard reduction potential**). These reduction potentials tell you which metal will corrode if you make a bi-metal cell. Electroplating can be explained using the analogy of 'un-corrosion'. If a solution of metal ions is non-standard the reduction potential changes in a way described by the **Nernst equation**. The reduction potential E when the molar concentration is  $M=C_{ion}$  instead of  $M=1$  is

$$E = E_0 + \frac{0.059}{z} \log(C_{ion})$$

where z is the valence of the ion and  $E_0$  the standard electrode potential.

Engineers have formulated a more practical, empirical ordering called a **galvanic series**. They rank engineering alloys by their propensity to corrode in common environments when joined to another metal. The ranking is such that any metal will become the anode (and corrode) if joined to any metal above it in the list, and it will become the cathode (and be protected) if joined to one below. Thus connecting dissimilar metals in either pure water or water with dissolved salts is a bad thing to do: corrosion cells appear that eat up the metal with the lower corrosion potential. It is even not necessary to have two metals, both anodic and cathodic reactions can take place on the same surface.

Corrosion can be selective. We have different types, such as **intergranular corrosion**. **Pitting corrosion** is the preferential attack on breaks in the natural oxide film. **Galvanic attack** at microstructural level appears in alloys with a two-phase microstructure. **Stress corrosion cracking** is accelerated corrosion, localised at cracks in loaded components.

**Corrosion fatigue** refers to the accelerated rate at which fatigue cracks grow in a corrosive environment.

## 17.7 Fighting corrosion

In fighting corrosion, there are four broad strategies:

- Good design
- Coatings
- Inhibitors
- Monitoring

For design we have the following guidelines:

- Allow for uniform attack
- Avoid fluid trapping
- Suppress galvanic attack
- Avoid crevices
- Consider cathodic protection
- Beware of stress corrosion and corrosion-fatigue
- Design for inspection and maintenance

We distinguish three types of **coatings**:

- Passive coatings (that only work if they are perfect)
- Active coatings (that work even if they are damaged)
- Self-generated coatings (that rely on alloying)

**Corrosion inhibitors** are chemicals that, when dissolved or dispersed in a corrosive medium, reduce the rate of attack.

Regular **inspection** allows early indications of corrosion to be detected. **Maintenance** (painting, recoating or repair) can then be carried out.

## **Chapter 20**

*Materials, processes and the environment*

## 20.1 Introduction and synopsis

**Design for the environment** is generally interpreted as the effort to adjust our present product design efforts to correct known, measurable environmental degradation. **Design for sustainability** is the longer-term view: that of adaptation to a lifestyle that meets present needs without compromising the needs of future generations.

## 20.2 Material consumption and its growth

Most materials are being consumed at a rate that is growing exponentially with time.

## 20.3 The material life cycle and criteria for assessment

CO<sub>2</sub>, SO<sub>x</sub>, NO<sub>x</sub> and other emissions (heat, and gaseous, liquid and solid waste) are collectively called environmental **stressors**.

## 20.4 Definitions and measurement: embodied energy, process energy and recycling energy

The **embodied energy** of a material is the energy that must be committed to create 1 kg of usable material. The **CO<sub>2</sub> footprint** is the associated release of CO<sub>2</sub>, in kg/kg. The **end-of-life potential** summarises the possible utility of the material at life's end: the ability to be recycled back into the product from which it came.

## 20.5 Charts for embodied energy

We can have diagrams that show solely the embodied energy per unit volume or per unit mass, or diagrams that show the embodied energy plotted against the strength or modulus.

## 20.6 Design: selecting materials for eco-design

The eco-impact of the use phase of energy-using products has nothing to do with the embodied energy of the materials themselves. Sometimes minimum eco-impact is achieved using minimum mass design.

The environmental consequences of the final phase of product life have many aspects. The ideal is summarised in the following guidelines

- Avoid toxic materials
- Examine the use of materials that cannot be recycled

- Seek to maximise recycling
- Seek to recover energy by controlled combustion when recycling is impractical
- Consider the use of biodegradable or photo-degradable materials

## 20.7 Materials and sustainability

Sustainable development is development that meets the needs of the present without compromising the ability of future generations to meet their own needs.

Global or national wealth can be seen as the sum of three components

- **net manufactured capital**: industrial capacity, institutions, roads, built environment, financial wealth (GDP)
- **net human capital**: health, education, skills, technical expertise, accumulated knowledge, happiness.
- **net natural capital**: clean atmosphere, fresh water, fertile land, productive oceans, accessible minerals and fossil energy

The sum of all three, the **net comprehensive capital**, is a measure of national or global wealth. **Strong sustainability** is development that delivers positive growth in all three capitals. **Weak sustainability** is development that delivers positive growth in the comprehensive capital.